



<b>AIRCRAFT:</b>	C-FNVK	<b>ATA:</b>	25-00	<b>COMPONENT CHANGE</b>	<input type="checkbox"/> NO <input type="checkbox"/> YES
<b>ISSUED BY:</b>	Planning	<b>Zone:</b>		<b>PART NUMBER:</b>	
<b>ISSUED DATE:</b>	22-Feb-2007	<b>Area:</b>	CABN	<b>SERIAL NUMBER:</b>	
<b>ORIGIN:</b>	HMV Task -	<b>Trade:</b>		<b>POSITION:</b>	
		<b>W.O.:</b>	712-3087		

<b>JOB</b>	SMP37-25-229 OP2
INSTALLATION OF AVIANOR GALLEYS IAW SMP37-25-229A.	

**REFERENCES**  
AV05145034-1, MDL05145042, Q-LSA05-054/D

**ACCESS**

PARTS REQUIRED			PARTS REQUIRED		
DESCRIPTION	PART NUMBER	Qty	DESCRIPTION	PART NUMBER	Qty
COFFEE MAKERS	50405-200	3	GALLEY R/H.	G4	1
Atlas standard 32 meal oven	8201-61-0000	1	GALLEY R/H.	G6	1
Atlas standard 48 meal oven	8203-61-0000	2			
GALLEY R/H.	G1	1			

RECTIFICATION / ACTION TAKEN	SIGNATURE.	#	DATE

AWS OPENED  NO  YES QUANTITY: \_\_\_\_\_ NON ROUTINE  NO  YES CARD # \_\_\_\_\_

<b>INSTALLED</b>	<b>PART NUMBER:</b>	<b>SERIAL NUMBER:</b>
------------------	---------------------	-----------------------

<b>INDEPENDENT CHECK</b> REQUIRED <input type="checkbox"/> YES <input type="checkbox"/> NO	<b>PITOT or STATIC CHECK</b> REQUIRED <input type="checkbox"/> YES <input type="checkbox"/> NO
<b>AUTH. PERSON:</b> _____ <b>ACA/AMO #:</b> _____	<b>AUTH. PERSON:</b> _____ <b>ACA/AMO #:</b> _____
The system has been inspected for correct assembly, locking and sense of operation in respect to the work accomplished.	The leakage rate of the system does not exceed the allowed tolerance.

**MAINTENANCE RELEASE**

**AUTHORIZED PERSON:** \_\_\_\_\_ **ACA/AMO #:** \_\_\_\_\_ **DATE** \_\_\_\_\_

The maintenance described above has been performed in accordance with applicable standards of airworthiness.

**TECH RECORD AUDIT:**

**BRADLEY AIR SERVICES - SERVICE MAINTENANCE PROCEDURE**

NO: 37-25-229A  
 REV: 1  
 ISSUED: April 3, 2006

PAGE 1 OF 3 PAGES

**DESCRIPTION**

INSTALLATION OF AVONOR GALLEYS.

Inspection  Repair  Modification  Servicing  Replacement

**EFFECTIVITY**

B737

**PLANNING**

Manhours req.  
Aircraft Downtime.

**REFERENCES**

AVIONOR LSTC Q-LAS05-054/D

**COMPLIANCE**

TO BE ACCOMPLISHED AT A CONVENIENT MAINTENANCE INTERVAL.

**REASON**

TO ALLOW MEAL CONTAINER CONFIGURED TROLLEYS TO BE UTILIZED.

REVISION # ISSUED	REASON	PREPARED BY:
1	Relocate water filter assy added.	Gary Beck

**PREPARED BY**

Gary Beck

DATE: March 31, 2006

**CHECKED BY**

*E Harris*

DATE: April 3/06

**APPROVED BY**

*[Signature]*

DATE: APRIL 3/06.

## MATERIAL LIST

<u>QUANTITY</u>	<u>PART NUMBER</u>	<u>DESCRIPTION</u>
1		G1 Galley R/H
1		G6 Galley R/H
1		G4 Galley R/H
A/R	NAS 1835-3 (or equivalent)	Potted Inserts
A/R	AN 525-(x)	Screws

ACCOMPLISHMENT INSTRUCTIONS	ACCOMPLISHED BY:
<b>NOTE: MARK N/A IF GALLEY IS NOT INSTALLED.</b>	
1. Install Avionor Galley at Position G1	
2. Install Avionor Galley at Position G4	
3. Install Avionor Galley at Position G6	
4. Transfer water filter assys to new galleys, locate in the upper link compartment. Use NAS 1835-3 inserts or equivalent and 525 screws to secure filter assy.	
5. Complete a leak and function check of galley as applicable.	

I certify that all applicable requirements stated in this Service Maintenance Procedure have been met and that Journey Log Book Entry "Avionor galley(s) installed IAW T.C. approval Q-LSA05-054/D, Bradley SMP 37-25-229A R1 refers" has been entered.

Signature of A.C.A. & Number (Endorsed on Type) or Inspector

SIGNATURE: \_\_\_\_\_

ACA# \_\_\_\_\_ AMO# \_\_\_\_\_

DATE: \_\_\_\_\_

**NOTE:** Any revisions or deviations to the accomplishment instructions of this SMP must be reported to Quality Assurance for amendments.